1983 Index

A

A.R. Wright Co., Sep: 75
Abex, Aug: 56
A-body wagons, Sep: 24
Accelerator pump, backfire-caused damage, May: 6
Accord, Jan: 52; Dec: 54
Accumulator pressure leakage, Jul: 30
AC-Delco, Feb: 53, 60; Mar: 58; Apr: 37; Nov: 36
AC PF25 filter counterfeits, Apr: 62
Aftermarket, Jan: 55
Air bags, Oct: 10, 50-51
Air conditioning, Jun: 14-19
  compressors, Jun: 19, 56
  cycling clutch
    orifice tube, Jul: 60-62
    switch, Jun: 16-17
  front/rear, Jun: 19
  in GM's, May: 23-28; Jun: 16-19, 56
  in Skylark, Apr: 62
  solenoid, Jul: 21-22
  specs, Aug: 78
  in Sportsman, Jun: 19
  spring lock couplings, May: 90; Jun: 15-16
  vacuum pump test, Jun: 19
  in Voyagers, Jun: 19
Air Injection Reactor(AIR), Jun: 30, 59-61
Alliance (AMC), May: 90; Sep: 29; Nov: 56
Allied Corporation, Apr: 45
Allstate Insurance, Apr: 38
All-Test, Inc., Oct: 43
Aluminum, Mar: 57; Oct: 33-34
Amco, Apr: 45
American Automobile Association (AAA), Oct: 63; Dec: 46
American Gas Association(AGA), Feb: 58
American Motors Corporation (AMC/Jeep/Renault)
  Alliance, May: 90; Sep: 29; Nov: 56
  CJ-5 discontinuation, Jun: 54
  Concord, Jun: 54
  diesel models, Feb: 55
  discontinued models, Jun: 54
  Encore ('84), Sep: 29
  ignition timing procedure, Mar: 41
  Jeep ('81), Mar: 68, 72; Sep: 30, 70
  1984 models, Sep: 29-30, 70
  small truck planned by, Jun: 54
  Spirit, discontinuation of, Jun: 54
  transmission fluid for, Sep: 32
Amoco, Jan: 51
Anaerobic gaskets, Dec: 23-25
Antifreeze, May: 12, 77; Oct: 34
AP Parts Company, Nov: 50
ARCO, Jan: 51; Mar: 57
Aries (Dodge)
  chuckling noise, Sep: 88
  front suspension noise, Jun: 35
  rear brake noise, Jun: 66-67
  transaxle problems, Oct: 60
Arrow Achievement Award recipients, Dec: 44-45
Arrow Automotive Industries, Apr: 37; Dec: 47
Arrow Pickup, upper control arm replace, Feb: 80
ASC, May: 67
Association of Diesel Specialists, Jul: 55
Atlantic Richfield, Jan: 51; Mar: 57
Audi, Jul: 59, Sep: 32
Audi 5000S, Jun: 47
Automobile Mechanic Training Evaluation Project(AMTEP), Apr: 43
Automotive Parts & Accessories Association(APAA), Feb: 53; Apr: 44; Sep: 61; Oct: 66
Automotive Service Councils, Inc., Jun: 43
Automotive Service Excellence(ASE), Jul: 36
Automotive Warehouse Distributors Association(AWDA), Sep: 76
Automotive Wholesalers of Illinois, Mar: 59

B

Backpressure, Sep: 64; Oct: 49
Balance shaft system, Sep: 61
Batteries
  Delco Freedom, Feb: 60-61; Nov: 36
  load testing, Feb: 60-61
  PVC caps for, Mar: 84-85
  recharging, Feb: 60-61
  Torque Starter, Jun: 68
Bearings, Sep: 48-49; Oct: 58
Bench bleeding, Dec: 28-29
Bendix Corp, Apr: 45; Aug: 56
Bendix SWC ('34), Oct: 63
Berger, Robert L., Aug: 64
Bidwell, Ben, Sep: 61
Bill Penn Memorial Scholarship, Nov: 50
Black box ignition in '84 Buicks, Jul: 36
BMW, Sep: 32
Body work, Mar: 53-55
Booker, Lawrence, E., Aug: 63
Booklets. *See* Catalogs, manuals, guides, booklets
Bowes Seal Fast Corporation, Dec: 46
Brake(s)
  back-up, Sep: 75
  binding, in Aspen ('77), May: 8
  bleeding, Dec: 27-32
  caliper, in Fairmont/Zephyr, Jun: 66
  charts for, May: 85
  do-it-yourself jobs, Apr: 63
  disc, Sep: 88; Oct: 61, 78; Dec: 49
  lining, Aug: 14-22, 55-56
  rear, noise, Jun: 66-67
  service standards and procedures, lack of, Aug: 6-7
  steel wool, Oct: 64
Brake fluids, silicone, Dec: 29-32
Brava ('80), Dec: 53
Buffum, John, Jan: 51
Buick
  all-front wheel drive lineup, Nov: 35
  Capital Electronic Product Center, Apr: 43

Century ('82-'83) tune up specs, Jan: 74
Delta 88 production, Jul: 38
Electra ('80), Dec: 49
electronic products of, Nov: 41-44
free advice by phone service, Sep: 62
fuel injection system, Jul: 36; Sep: 21
ignition systems
black box, Jul: 36
distributorless, Sep: 21; Nov: 28-32, 45-48
LaSabre ('80), blower motor, Dec: 49
light throttle detonation, Jul: 57
Regal, Jul: 37
Skylark. *See* **Skylark (Buick)**
starting motor specs, May: 106
Bur, Thomas G., Aug: 63
Business interruption insurance, Nov: 57-58
Bussman Division of McGraw-Edison, Apr: 45

C

C-3 (GM) engine control system
in Cutlass ('81), May: 10, 75
tester, Apr: 22-25, 52-57; Dec: 63-64
basic functions, Apr: 22-25, 52-55
design, Apr: 55-57
Carbiolet, Dec: 44
Cadillac
cold engine noise, Jun: 66
Eldorado Touring Coupe ('83), Jan: 51
front/rear wheel drive models, Aug: 54
front-wheel drive limo, Sep: 76
ignition timing, Mar: 36-37
increase in new cars, May: 85
manifold absolute pressure(MAP) sensor line icing, Jan: 61
1983 sales, Dec: 46
power steering/power brake failure, May: 16, 67
Sedan DeVille alignment, Jan: 8-9
CAFE(corporate average fuel economy), Feb: 48; Jun: 53; Aug: 51; Sep: 60; Oct: 42; Nov: 37
Caldwell, Phillip, Aug: 63
California
car sales in, Jul: 38
design studios in, Jul: 38
as import sales predictor, Jan: 17-18
maximum allowable HC and CO limits, Mar: 90
tax laws, conflict in, Jun: 54
Calipers, Jun: 70
dust boots, installation of, Feb: 31-39
Camry ('83), Mar: 57
Canadian government, Feb: 54
Capri (Mercury)
brake caliper changes, Jun: 66
fluid checking, Nov: 56
stalling while parking, Dec: 48
Caprice ('81) diesel, Dec: 49
Carburetors
adjustment specs, Mar: 90; Apr: 70; Dec: 70
gasket, Feb: 68
mounting, Feb: 9, 19
seminar on, Nov: 50
subsystems and deceleration valves, Jul: 21-24
two barrel, rebuilding, Aug: 24-32
variable venturi, Mar: 18-29
adjustments, Mar: 22-24
reassembly, Mar: 26-29
teardown procedure, Mar: 21-22
Car Care Council(CCC), Sep: 78
Car Carrier, Jul: 65
Carter Automotive Division, Aug: 61
Catalogs, manuals, guides, booklets
alignment types poster, Nov: 67
Bearing Failure Trouble-Shooting Guide, Sep: 100
Borg-Warner Brand ignition catalog, supplement, Apr: 64
brakes, Jun: 69
EIS Brake Manual, Jul: 68
service manual, Mar: 82
Carter Climatrol Cooling and Heating Parts, Aug: 68
Carter Precision Remanufactured Electrical Components, Dec: 62
calipers catalog, Jan: 63
cap and thermostat catalog, Jan: 64
equipment catalog, Mar: 84
Import/Domestic Cylinder Head Specification Manual, Oct: 71
imported parts catalog, May: 101
"Lamp & Flasher Replacement Guide" (update), Oct: 71
Mighty Distributing System of America technical manual, Jul: 67
Motor Auto Repair Manual 1984, Oct: 68; Dec: 60
Motor Emission Control Manual, Mar: 75, 90; Sep: 94; Oct: 39
Motor Imported Car Parts & Time Guide, Aug: 67; Oct: 69
Motor Imported Car Repair Manual, Jul: 65
Motor Parts & Time Guide 1984, Nov: 61
Motor Truck & Diesel Repair Manual, Apr: 64
Motor Wiring Diagram Manual, Jun: 71
"New and Remanufactured Clutches for Passenger Cars and Light Trucks" (Cat. No., C-83; BWD Automotive Corporation), Oct: 75
OTC Tools & Equipment Supplement, Aug: 67
parts catalog, Feb: 71
"Quick Course in Car Care—Cooling System," Sep: 98
Raybestos Brake Products Catalog Supplement, Dec: 58
remanufactured injection pumps and nozzles catalog, Dec: 62
Saab service bulletin no. 04/83-624, Sep: 1
Strut Cartridges and Assemblies for Domestic and Import Passenger Cars, Nov: 64
suspension systems poster, Nov: 67
TRW Automatic Transmission Parts catalog, Dec: 67
Catalytic converters, Oct: 48; Dec: 14
Center for Auto Safety(CAS), Oct: 41
Ceres three-wheeler, Jun: 41
Champion Parts Rebuilders, Inc., Mar: 59; Sep: 79
Champion Spark Plug Co., Jul: 55; Oct: 63
Chevette (Chevrolet)
fuel system problems, Aug: 10-11; Nov: 10
starting motor, tune up, and wheel alignment specs, May: 106
steering wheel shakiness, Feb: 8
Chevrolet
Caprice ('81) diesel, Dec: 49
Celebrity ('82-'83) tune up specs Jan: '74
Chevette. *See* Chevette (Chevrolet)
Citation, Jun: 35, 36
Corvette. *See* Corvette (Chevrolet)
dwell reading, Oct: 61
EGR valves, Sep: 88
franchising by, Jun: 51
Impala ('81) diesel diode service, Dec: 49
Malibu. *See* **Malibu (Chevrolet)**
manifolds, intake adapter, for, Mar: 87
M-van introduction, Sep: 59
Nova ('68), oil dilution, Apr: 8-9
3.8 liter cold driveability problems, Dec: 12-13
truck sales position, May: 67
V6 engine, Mar: 87-88
wheel alignmnt for '69-'70s, Oct: 78
Chicago Rawhide, Apr: 45
Choke, electric and hot air, Jul: 22-23
Chrysler
A-460 transaxle, Oct: 60
accelerator pump adjust, May: 91
aspirator valve failure, Nov: 18-19
balance shaft system, Sep: 61
cold driveability problems, Aug: 10
competition with GM/Toyota joint venture car, May: 83
Cordoba and Mirada discontinuation, Jun: 54
design studios, Jul: 38
diesel program cancellation, Feb: 54
digital-circuit ignition components and RF interference, Apr: 62
engine oil leaks, Jan: 62-63
400, Sep: 88
front wheel drive, Jun: 36; Jul: 57,

70; Aug: 75
fuel injection, electronic, Nov: 21-26
GM product line-up and, Apr: 36
gypsy packagers, suit against, Dec: 35
ignition timing procedures, Mar: 37-38
LeBaron, Sep: 88
marketing strategy, Oct: 44
Mitsubishi relationship, Jan: 28
1984 models, Jul: 38; Sep: 25-26
1983 models, Feb: 64
partnership deals of, Sep: 61
problems due to profit, Sep: 59
ranking goal of, Nov: 36
steering knuckle replace, Mar: 90
with throttle body injection(TBI), Sep: 26
T-115 Van and Wagon, Sep: 25
transaxle, manual, Feb: 64
transmission fluid for, Sep: 32
trucks, hesitation or sag, Dec: 49
two-passenger model, Jul: 36; Oct: 44
2.2-liter engines, Oct: 61
unemployment figures and, Oct: 43
valve spring change, Aug: 75
Vega ('77) overheating, Oct: 16, 53
-VW deal collapse, Oct: 42
CIS. *See* Continuous injection system
Clutch
installation, Sep: 50
release bearing noise test, Sep: 49
repair tips, Sep: 45-50
self-adjusting, in Starlet ('81-'83), Dec: 53
squeal test, Sep: 49
Colt ('80), Dec: 14
Compounding, Mar: 54-55
Compressors
a/c, Jun: 19, 56
MacPherson strut, Feb: 71
Computerization, Jan: 56; Feb: 47; Mar: 64; Jul: 68
Computer listing, Jul: 53
Consumer agencies, Jun: 52
Contact lenses, use during welding, Jun: 52; Jul: 37
Continuous injection system(CIS), Jul: 27-32
hot start problems, Jul: 28-29; Oct: 12, 52
Convertibles, Oct: 64
Coolant, worn out, Oct: 33-36, 55
Cooling system sealants, Jun: 69
Corvette (Chevrolet)
disc brake service, Oct: 61
1983 model, Feb: 25-27, 42, 66; May: 85; Jun: 52
Cosworth racing engine, May: 60-62
Counterfeiting, May: 85; Jun: 6; Sep: 61; Dec: 34-35
Credit cards, Apr: 6, 66
Cruise control, electronic, Nov: 42
Customers, flexibility with, Jun: 12
Cylinder power balance test, May: 78-79

D

D50 upper control arm replace, Feb: 80
Dallas Grand Prix, Nov: 50-51
Dana Corporation, May: 67; Jul: 53
Datsun, Sep: 32; Dec: 54. *See also* Nissan
Dealer(s)
consumer agencies and, Jun: 52
diesel-to-gas engine swapping by, Nov: 37
dual, Oct: 43
foreign car makers and, May: 85
possible Chevrolet-Toyota cooperation, Jul: 37
price increases and, Jul: 35
service recommendations, Mar: 64
Dealer Advertising Awards, Dec: 46
Delaney, Michael J., Aug: 63
Detroit
crisis in, theories of, Jan: 6-7
excess plant capacity of, Jan: 57
proprietary tools elimination by, Aug: 51
tool makers and, Jan: 55
Detroit Grand Prix, Jul: 38
Dexron II, Sep: 32
Diesel engines. *See* Engines, diesel
Diesel fuel, contaminated, Dec: 48
Dieseling, Jul: 21
DiGard racing team, Aug: 36-47, 57-58
Distributor
HEI-equipped, May: 91
pickups, in '78-'79 Omni/Horizon, Feb: 62
rotors, in Toyota, Sep: 82
Dodge
Aries. *See* Aries (Dodge)
Aspen ('77), Feb: 8; May: 8
Mirada, discontinuation of, Jun: 54
Monaco ('77), handling, Feb: 8-9
Omni. *See* **Omni (Dodge)**
pickups, diesel engine for, Oct: 66
pistons, pins, rings, crankshaft and bearing specs, Nov: 70
Rampage, Jul: 41-48
vans ('79-'82), inoperative starter relay, Jun: 67
Dorman Products, Dec: 46
Drive train, Tempo/Topaz, Apr: 28-31, 59
Du Pont Company, Dec: 46
Dust boots, Feb: 32-39; Mar: 77

E

Early Fuel Evaporation (EFE) system, Jun: 26-30, 58-59
Echlin Inc., Feb: 47
"Editor's Report"
accelerator pump, backfire-caused damage, May: 6
brake system standards and procedures, lack of, Aug: 6-7
competition with mass merchandisers and tire chains, Jul: 6, 51
Detroit's crisis, lessons for aftermarket, Jan: 6-7
factory engineer's ignorance of service business, May: 6, 72
Gun Control Act of 1968, Dec: 10-11
gypsy parts update, Jun: 6
lifetime service guarantees, Jun: 6
mechanics' working conditions, Feb: 6-7
passive restraints, Oct: 10, 50-51
plastic engines, Nov: 8-9
protectionist legislation, Mar: 8
refusal to pay credit card charges, Apr: 6, 66
X-car recall, Sep: 6, 63
Edmund, Stan, Aug: 64
EGR valves, Feb: 15-22, 41; May: 20; Sep: 88
EIS, Aug: 56
Electrical systems, seminar on, Nov: 50
Electronic Engine Control(EEC), Mar: 38-41; Jun: 10
Emission controls in GM cars. *See* General Motors Corporation (GMC), emissions controls systems
Engines
aluminum, Nov: 36
Chevy V6, Mar: 87-88
Chrysler, oil leaks in, Jan: 62-63
compartment component tagging, proposed, Mar: 64
Cosworth racing, May: 60-62
decreased development of, Jan: 57
diesel
direct injection, Nov: 50
-to-gas swapping, Nov: 37
head gaskets for, May: 38-39; Aug: 75
hot starting problems, Feb: 62-64
piston, pins, rings, camshaft and bearing specs, Nov: 70
for small pickups, Oct: 66
for Tempo/Topax, Jul: 38
tightening specs, Nov: 70
turbocharging, Apr: 14-18, 46-50
valve specs, Dec: 70
Ford V8, Feb: 62; May: 58
460 cid main bearing knock, Aug: 70
Japanese, kits for, Jan: 73
Honda, rebuilding, Oct: 27-32, 56-58
Offenhauser, May: 57-60
plastic, Nov: 8-9
for Tempo/Topaz, Jan: 58; Jul: 38; Sep: 62
turbocharged, Sep: 24, 25-26
3.8 liter, spark plug change, Feb: 62
tri-fuel, Jul: 37
2.2 liter oversize camshaft markings, Oct: 61
2.5 liter gear noise, Nov: 56

Equipment. *See* Tools, repair kits, equipment
Equipment suppliers, computer-aided service and, Mar: 64
Escort (Ford)
brake booster replacement, Jul: 57
brake specs, Jun: 78
diesel model, Sep: 29
master cylinder replace, Jul: 70
piston markings, Oct: 61
power, lack of, Sep: 88
radiator of, May: 41-42
rear wheel bearing adjust, Aug: 78
steering wheel return, Jul: 57
turbocharged, Sep: 28-29
Evaporative Control Systems(ECS), Jan: 44-46
valves, May: 20; Sept: 88
Evaporators, GM, Jun: 16-19
Exhaust Gas Recirculation(EGR) system, Feb: 15-22, 41
Exhaust repair market, Mar: 60
Exhaust systems
clamping vs. welding in, Oct: 48
restricted, Dec: 48
small car, Oct: 47-49
Toyota, Mar: 47
EXP (Ford)
brake specs, Jun: 78
continuation of, Jul: 35
master cylinder replace, Jul: 70
radiator of, May: 41-42
rear wheel bearing adjust, Aug: 78
turbocharged version of, Jul: 53
Exxon, Jan: 51

F

Facom Tools, Inc., May: 678
Fairmont (Ford)
brake caliper changes, Jun: 66
driveability and stumble problem, Apr: 8; Jul: 10
stalling while parking, Dec: 48
Fair Practices in Automotive Products Act (H.R. 5133), Mar: 8
Fan belts, Apr: 44
Faulkner, Dale, Aug: 64
Federal-Mogul, May: 86
Fel-Pro, Dec: 45
Felt, needled, Sep: 32-41
Fender covers, Feb: 71
Fiat
timing belt replace, Feb: 80
transmission fluid for, Sep: 32
"Field Fixes"
batteries, recharging, Feb: 60-61
Ford cycling clutch orifice tube a/c, Jul: 60-62
oil leaks, Jan: 62-63; Sep: 92
spark knock, Mar: 70, 73
THM leak diagnosis, Dec: 55
Toyota automatic transmissions, May: 94-96; Jun: 63-65
Fiesta (Ford)
on-car wheel balancing, Jul: 59
power and mpg loss, Dec: 54
turn signal flashers, Sep: 82
Filters
AC PF25, counterfeit, Apr: 62
oil, in Toyotas, Mar: 50
transmission, Sep: 31-41
Firestone, Feb: 48; Apr: 37; May: 83; Dec: 36
Fleet operators, Jan: 52
Float bowl, fuel loss in, Jul: 10
Florida Automotive Service Councils, Inc., Mar: 59; Nov: 51-53
Flywheel inspection, Sep: 49-50
FMC, Dec: 47
Ford, Edsel Bryant, II., Sep: 29
Ford
air conditioners, May: 90; Jun: 15-17, 56; Jul: 60-62
balance shaft system, Sep: 61
big car sales, reaction to, Aug: 51
CAFE(corporate average fuel economy) requirement and, Jun: 53; Aug: 51; Sep: 60
clutch repair tips for '81s, Sep: 49
counterfeiting problems, Dec: 34
curtailment of projects, Feb: 54
diesel model offerings, Feb: 55
detonation problems in '80s, Sep: 90
Econoline, Jun: 55
Electronic Engine Control(EEC), Mar: 38-41; Jun: 10
engines. *See* **Ford engines**
Escort. *See* **Escort (Ford)**
EXP. *See* **EXP (Ford)**
F350 ('79), fuel vaporization problems, Nov: 10-15
Fairmont. *See* **Fairmont (Ford)**
Fiesta. *See* **Fiesta (Ford)**
FM radio interference in '77-'81s, Oct: 61
Fram vs., Jun: 53
fuel economy, Mar: 66
fuel injection systems, electronic, Nov: 28
full-lock turn stall in '78-'81s, Sep: 90-91
GM product line up and, Apr: 36
Granada, Jun: 36; Dec: 48, 49
ignition timing procedures, Mar: 38-40
LTD, Jul: 36
LTS-9000 armored truck, Jun: 41
methane car project, Feb: 58-59
Mini Van, May: 68
with NASCAR blocks, Mar: 86-87
1984 models (domestic), Sep: 26-29, 59
Olds' challenge to, Nov: 37
parts
division hotline, Jun: 41
interchangeable, Apr: 38
power rack and pinion replacement, Mar: 68
overseas sources, interest in, Nov: 35
problems due to profits, Sep: 59
robots, use of, Jul: 20
rust prevention process, May: 86
San Jose plant closing, Jan: 56
service, Mar: 63; May: 84; Jun: 6, 41, 51; Oct: 22
simulated voice alerts cancellation, Sep: 60
spark retard module, Mar: 40
strut diagnosis, Jan: 61
Tempo. *See* **Tempo (Ford)**
Tempo/Topaz support, Nov: 53
test drive program, Dec: 46-47
Thunderbird. *See* **Thunderbird (Ford)**
transmission fluid for, Sep: 32
unemployment figures and, Oct: 43
van ('78), fuel vaporization problems, Nov: 10-15
wheel alignment specs, Jan: 74
Ford engines
460 cid ('75-'77), main bearing knock, Aug: 75
planned optional, Jun: 52
Tempo/Topaz diesel, Jul: 38
3.8 liter, spark plug change in, Feb: 62
V8, Feb: 62; May: 58
Foreign car makers, dealers and, May: 85. *See also* **Imported cars**
"4-Wheeling With Ford," Apr: 37
Fram, Jun: 53; Aug: 53
Front-wheel vs. rear-wheel drive, Jul: 37
Fuego Turbo, wiring abrasion, Dec: 54
Fuel
CIS hot start problems and, Jul: 29-32
diesel, Apr: 65; Dec: 48
hydrogen, Mar: 88
loss, in float bowl, Jul: 10
methane, Feb: 58-59
price of, Apr: 35; Jun: 41
Fuel distributor leakage, Jul: 32
Fuel heaters, Apr: 65
Fuel injection systems
Buick, Jul: 36; Sep: 21
continuous(CIS), Jul: 27-32
direct, in diesels, Nov: 50
electronic, Sep: 21, 28; Nov: 21-26, 41, 42
in GMs, Sep: 24
throttle body(TBI), Mar: 33; Sep: 26
Fujitsu Fanuc, Ltd., Jul: 20

G

Gannon, Kevin, D., Jul: 55
Garrett Corporation, Feb: 47
Gaskets
anaerobic, Dec: 23-25
carburetor, Feb: 68

compounds, Jan: 72-73; Apr: 64
head, May: 31-39
chemical sealants, May: 39
in diesel engines, May: 38-39
of Hondas, Oct: 57-58
installation tips, May: 33-38
retorquing, Oct: 52
remover, Jun: 69
soft, Dec: 23-25
Gasoline nozzle notch device, Jan: 52
Gasoline vapors, danger of, Oct: 63
General electric, Sep: 76
General Motors Corporation(GMC)
A-body wagons, Sep: 74
air conditioning, May: 23-28; Jun: 16-19, 56
audio offerings, Sep: 79
C-3 computer diagnostic system testers, Apr: 21-25; May: 10, 75; Dec: 63-64
CAFE(corporation average fuel economy) and, Feb: 48; Jun: 53; Sep: 60; Oct: 42
C-car production delay, Oct: 41
computer command control, Jul: 70
consolidation of manufacturing, Mar: 65
curtailment of projects, Feb: 54
design studios, Jul: 38
diesel fuel filter test, Sep: 91
diesel models, Feb: 55; Dec: 49
ECM malfunction in '82-'83 fuel injection models, Sep: 81
emissions controls sytems
Air Injection Reactor(AIR), Jun: 30, 59-61
carburetor subsystems and deceleration valves, Jul: 21-24
Early Fuel Evaporation(EFE), Jun: 26-30, 58-59
Exhaust Gas Recirculation(EGR), Feb: 15-22, 41
Positive Crankcase Ventilation (PCV), Jan: 41-44
preheated intake air system, Jan: 46-49
Pulse Air Injection Reactor(PAIR), Jun: 30, 59-61
vacuum spark control devices, Oct: 37-39
engines
aluminum, Nov: 36
5.7-liter diesel, head gasket changes, Aug: 75
tri-fuel, development of, Jul: 37
2.5-liter, timing gear noise, Nov: 56
evaporators, Jun: 16-19
exclusive bodies by division, Feb: 53; Oct: 44
fuel injection system, Sep: 24
ignition systems, Mar: 33-36; May: 91, Jul: 36
import restrictions, position on, Nov: 35
in-company suppliers and, Jan: 58
N-cars, Nov: 53
New York City Transit Authority bus contract of, Feb: 47
1984 models, Sep: 20-24
overseas parts sources and, Nov: 35
pickups and 4 X 4 recall, Feb: 64
product lineup, Apr: 36
problems due to profits, Sep: 59
reaction to big car sales and, Aug: 51
restricted exhaust in '82-'83s, Dec: 48
robots, use by, Jul: 20
roller hydraulic lifter, Dec: 51-52
search for fuel economy regulation loopholes, Aug: 51
service, May: 86; Aug: 53; Nov: 37
T-cars, Feb: 55
transmissions, Apr: 62; Sep: 32; Oct: 61; Dec: 49
unemployment figures and, Oct: 43
X-body cars. *See* **X-cars (GM)**
General Motors Corporation-Toyota partnership
Chrysler and, May: 83
consequences of, Dec: 34-35
"foreign imports" and, Apr: 38
in-house reactions to, Sep: 60
Japanese production secrets and, Apr: 36
negotiations of, Jan: 57
parts business and, Apr: 35
Gillis, Alan, Aug: 63
GNB Batteries (company), May: 67
Goodyear, May: 67; Jul: 54
Green Light Company, Sep: 60
Guaranteed Parts Company, Aug: 62; Sep: 75
Guarantees
check, Mar: 67
lifetime service, Mar: 63; May: 84; Jun: 6
Guides. *See* **Catalogs, manuals, guides, booklets**
Guns, law and, Dec: 10-11, 18-21

H

Handbook, 60th ed. — '83
brake data, cars ('80-'83), 67-72
cooling system and capacity data ('80-'83), cars, 86-101
American Motors, 86
Buick, 86-87
Cadillac, 88
Chevrolet, 88-94
Chrysler, 94, 95-96
Dodge, 95
Ford, 96-98
Lincoln, 98-99
Mercury, 96-98
Oldsmobile, 99-100
Pontiac, 100-101
engine torque wrench data ('80-'83), 112-115
cars, 112-113
trucks, 114-115
farm tractor tune-up, 121-127
new products, 140-148
piston and rod assembly ('80-'83), 73-81
cars, 73-76
trucks, 77-81
pushing and towing automatic drive cars, 139
spark plug application chart, 128-137
tune up data, cars ('80-'83), 3-53
American Motors, 3-4
Audi, 49-50
Buick, 5-6, 18-19
Cadillac, 7
Chevrolet, 10-18
Chrysler, 20-24
Datsun/Nissan, 43-45
Dodge, 45
Fiat, 46
Ford, 25-34, 46
Honda, 46-47
Isuzu, 47
Jaguar, 47
Lincoln Continental, 35-36
Mazda, 47-48
Mercedes-Benz, 48
Mercury, 25-34
MG, 48
Oldsmobile, 37-38
Olds Cutlass Ciera, 18
Olds Starfire, 19
Peugeot, 48
Plymouth, 49
Pontiac, 18-19, 39-42
Porsche, 49-50
Renault, 50
Saab, 50
Subaru, 50-51
Toyota, 51-52
Triumph, 52
Versailles, 35-36
Volkswagen, 52-53
Volvo, 53
tune up data, trucks ('80-'83), 54-56
Chevrolet, 54-57
Dodge, 58-60
Ford, 60-65
GMC, 54-57
international, 65
Jeep, 65-66
Plymouth, 58-60
valve timing marks ('80-'83), 83-85
wheel alignment data ('80-'83), cars, 102-106, 107-111
H.K. Porter, Aug: 56
Harabosky, Serge, Oct: 32
Head gaskets, May: 31-39
chemical sealants, May: 39
in diesel engines, May: 38-39
of Hondas, Oct: 57-58
installation tips, May: 33-38
retorquing, Oct: 52
Heaters, fuel, Apr: 65
Hein-Werner, Mar: 66

Henschen, Mark M., Jul: 54
Hertz, limited warranties of, Mar: 58
Holley 6520 adjustment specs, Jan: 74
Holtzberg, Matthew, Nov: 8-9
Home-office deductions, May: 102-103
Honda
auxiliary valve, plugged, Oct: 32, 56
bearing matching for, Oct: 58
camshaft, Oct: 29-32
engine rebuilding, Oct: 27-32, 56-58
gauge malfunction, Sep: 82
head gaskets of, Oct: 57-58
oil consumption of, Oct: 56
oil pump problems, Oct: 57
oil strainer in, Oct: 38
powerplant applications, Oct: 29
radial tire vibration, Jun: 37
rod bearing problems, Oct: 56-57
servicing, Jan: 31-39
specialty equipment, Oct: 32
thrust bearing problems, Oct: 57
transmission fluid for, Sep: 32
Honda Accord, Dec: 54
U.S. built, Jan: 52
Honda Civic CRX, Nov: 50
Horizon
carburetor mounting, Feb: 19
disc brake piston, Sep: 88
disc brake service, Dec: 49
distributor pickup, Feb: 62
front suspension noise, Jun: 25
isolator plates, Jul: 10-11
mileage problems, Mar: 12, 56
rear brake noise, Jun: 66-67
throttle shaft wear, Oct: 12
transaxle problems, Oct: 60
vacuum leak, Jul: 10-11
wheel bearing failure, Jan: 61
Hoses, sales of, Apr: 44
Hot start problems, CIS, Oct: 12, 52
Hot-start relay, Jul: 32
Hunter Engineering, Dec: 46
Hydraulic lifters, Feb: 62; Dec: 51-52
Hydrogen fuel, Mar: 88
Hydrometer, Freedom battery's, Feb: 61
Hyundai, Dec: 44

I

Ideal Corporation, Oct: 66
Ignition systems
digital circuit, Apr: 62
distributorless, Sep: 21, 24; Nov: 28-32, 45-48
electronic, Mar: 46; Nov: 41-42
GM, Mar: 33-36; May: 91; Jul: 36, 57
timing procedures, Mar: 33-41
AMC, Mar: 41
Cadillac digital display, Mar: 36-37
Chrysler, Mar: 37-38
Ford, Mar: 38-40
GM, Mar: 33-36
Olds Misar, Mar: 37
VW, Mar: 41
Imported cars
1983 models, Jan: 16-28
California as predictor of sales of, Jan: 17-18
general sales trends, Jan: 18
Japanese sales, Dec: 45
Mazda, Jan: 22-26
Mitsubishi, Jan: 28
Nissan, Jan: 20-21
Porsche, Jan: 27-28
Toyota, Jan: 20
Volkswagon, Jan: 26-27
restrictions on, Aug: 52; Nov: 35
Impulse coupe, (Isuzu), Aug: 61
Independent Automotive Service Assn., Mar: 59; Jun: 43
Independents, Mar: 60; Sep: 60-61
Indianapolis 500, May: 50-53, 57-62
Insurance
Allstate, Apr: 38
auto, Mar: 57
business interruption, Nov: 57-58
radial tires and, Mar: 57
vehicle theft and, Feb: 54
Investment tax credit, Sep: 83, 87
Iococca, Lee, Sep: 61
Isuzu, transmission fluid for, Sep: 32
impulse coupe, Aug: 61

J

Jaguar, Jan: 51; Sep: 32; Dec: 46
Januar XJ6 ('83), Jan: 28
Japan
export policy of, Aug: 52
import quota on, Oct: 43
increased sales, Dec: 45
parts from, Dec: 35
production secrets, Apr: 36
success of, Jan: 6
Japan Automobile Manufacturers Association, Dec: 45
JC Penney, Mar: 65

K

Kwik-way Industries, Inc., Aug: 62-63

L

Lanair, Inc., May: 69
Lang, Allen, Aug: 64
Laser/Daytona ('84), Sep: 25
Lathrop, Ken, Aug: 63
Lawyers, Jul: 38
LeCar discontinuation, Jun: 54
Lee Filter, Sep: 79
Legislation, local content, Mar: 8; Aug: 52
LeSabre ('80), blower motor, Dec: 49
Lifters, hydraulic, Feb: 62; Dec: 51-52
Lincoln
full-lock turn stall, Sep: 90-91
Mark IV, air suspension, Apr: 45
Mark VII, Jul: 55, Sep: 26-28
rack and pinion replacement parts, Mar: 68
strut diagnosis, Jan: 61
Littlefuse, Inc., May: 85
LN7 (Mercury)
brake specs, Jun: 78
discontinuation of, Jul: 35
Master cylinder replace, Jul: 70
radiator of, May: 41-42
rear wheel bearing adjust, Aug: 78
Loans, low interest, Jun: 53
"Longest Day of Nelson Ledges," Aug: 61
Loss coverage, Feb: 73-74
Lotus Eclat 2 + 2, Jan: 51
Lotus Performance Cars, Jul: 54
Lotus racing team, Mar: 57
LUV ('74) pickup linkage, Jan: 9
Lynx (Mercury)
brake booster replace, Jul: 57
brake specs, Jun: 78
diesel, Sep: 29
master cylinder replace, Jul: 70
piston markings, Oct: 61
power, lack of, Sep: 88
radiator of, May: 41-42
rear wheel bearing adjust, Aug: 78
steerwing wheel return, Jul: 57

M

McCord Gasket Division, Mar: 59
MacPherson struts
checker, Jan: 69
compressors, Feb: 71
diagnosis, Jan: 61
front assembly ID, Jun: 78
support mountings and bearings for, Apr: 65
McQuay-Norris, Dec: 47
Malibu (Chevrolet)
mixture problems in '82s, Sep: 64
pinging in '81s, Jun: 10, 55
Manuals. *See* **Catalogs, manuals, guides, booklets**
"Manual Update"
air conditioning specs, Aug: 78
Arrow Pickup upper control arm replace, Feb: 80
Buick starting motor specs, May: 106
California HC & CO limits, Mar: 90
carburetor adjustment specs, Apr: 70; Dec: 70
Celebrity ('82-'83) tune up specs,

Jan: 74
Century ('82-'83) tune up specs, Jan: 74
Chevette starting motor, tune up, and wheel alignment specs, May: 106
Chevrolet ('69-'70) wheel alignment procedure, Oct: 78
Chrysler
FWD oversize camshaft bearing ID, Jul: 70
steering knuckle replace, Mar: 90
D50 upper control arm replace Feb: 80
Dayton-Walther dual piston disc brake caliper rebuild, Oct: 78
Dodge pistons, pins, rings, crankshaft & bearings specs, Nov: 70
Escort/EXP
brake specs, Jun: 78
master cylinder replace, Jul: 70
rear wheel bearing adjust, Aug: 78
Fiat timing belt replace, Feb: 80
Firebird ('82-'83) radio replace, Mar: 90
Ford wheel alignment specs, Jan: 74
front strut assembly ID, Jun: 78
GM computer command control, Jul: 70
Holley 6520 adjust specs, Jan: 74
International diesel engines
valve specs, Dec: 70
piston, pins, rings, crankshaft & bearings specs, Nov: 70
tightening specs, Nov: 70
LN7/Lynx
brake specs, Jun: 78
master cylinder replace, Jul: 70
rear wheel bearing adjust, Aug: 78
Mercury wheel alignment specs, Jan: 74
Motorcraft model 740 carburetor adjust specs, Mar: 90
Olds Cutlass Ciera tune up specs, Jan: 74
Plymouth pistons, pins, rings, crankshaft, and bearings specs, Nov: 70
Pontiac 1000 starting motor, tune up, and wheel alignment specs, May: 106
Pontiac 6000 ('82-'83) tune up specs, Jan: 74
Pontiac radial replace, Mar: 90
Porsche
cooling system and capacity data, Feb: 80
tune up specs, Feb: 80
Quadrajet M4M series adjust specs, Sep: 102
Ram 50 upper control arm replace, Feb: 80
Rochester 2SE & E2SE adjust specs, Apr: 70
steering knuckle replace, Jun: 78
Toyota starter replace, Nov: 70
Matsushita Electric Trading Company, Apr: 45
Mature industry theory, Jan: 6-7
Mazda
B2000 Sundowner ('83), Jun: 41-42
B2200 diesel pickup, Apr: 18
GLC ('83), Jan: 22
1983 imported models, Jan: 22-26
RX-7, May: 67
626 ('83), Jan: 22-26
transmission fluid for, Sep: 32
Mercedes-Benz
air bag option, Oct: 10, 50-51
discontinued models, Sep: 60
engine preheater, Sep: 75
transmission fluid for, Sep: 32
turbo wastegate check, Sep: 54-56
two-seaters, Oct: 63
Merchandisers, mass, Jul: 6, 51
Mercury
Capri. *See* **Capri (Mercury)**
Cougar, Feb: 47; Jun: 36; Dec: 48, 49
full-lock turn stall, Sep: 90-91
LN7. *See* **LN7 (Mercury)**
Lynx. *See* **Lynx (Mercury)**
Montero ('83), Mar: 57
power rack and pinion replacement parts for '79s, Mar: 68
strut diagnosis, Jan: 61
Topaz. *See* **Topaz (Mercury)**
wheel alignment specs, Jan: 74
Zephyr. *See* **Zephyr (Mercury)**
Methane fuel, Feb: 58-59
MG, transmission fluid for, Sep: 32
Mileage record, Aug: 61
Millen, Steve, Jul: 53
Mini-Baja West, Sep: 76
Minit-Lube, Feb: 47
Miser (Plymouth)
ignition timing procedures, Mar: 37
spark knock in, Mar: 68
Mr. Gasket Co., Jul: 55
Mitsubishi
-Chrysler relationship, Jan: 28
Cordia ('83), Jan 27, 28
1983 models, Jan: 28
Starion ('83), Jan: 26, 28
Tredia ('83), Jan: 28
transmission fluid for, Sep: 32
Mobile Air Conditioning Society Convention and Trade Show (MACS), Jun: 15
Monroe, Dec: 47
Moog Automotive Training Center, Mar: 59
Motor homes, high-mileage, Mar: 88
Motor Vehicles Manufacturers Association, The, Mar: 59
Muffler(s), rear mounted, Oct: 48
Muffler market, Sep: 61
Mustang (Ford)
brake caliper changes, Jun: 66
fluid checking, Nov: 56
GT, Jun: 75
stalling while parking, Dec: 48
SVP, Sep: 28; Oct: 63-64

N

NATEF(National Automotive Technicians Education Foundation), Apr: 43
National Association of Wholesaler-Distributors(NAW), Oct: 64
National Automotive Parts Association (NAPA), Feb: 48; Nov: 50; Dec: 33
National Highway Traffic Safety Administration(NHTSA), Feb: 55; Sep: 75; Oct: 10, 50
National Institute for Automotive Service Excellence(NIASE), Jan: 56; Mar: 66; Apr: 43; May: 86; Jul: 36, 55; Oct: 63
National Pit Crew Championship, Aug: 47
National Tire Dealers & Retreaders Association, Inc.(NTDRA), Sep: 78-79
N-cars (GM), Nov: 53
NCR Corporation, Sep: 75
Nerlinger, John W., Jul: 55
New competition theory, Jan: 7
NGK Spark Plug Company, Jun: 43
944 ('83), Jan: 26, 27-28
Nissan, Jan: 20-22; Feb: 56; Sep: 62. *See also* Datsun
Pulsar NX, Jan: 22; Aug: 63
Sentra ('83), Jan: 20-22

O

Ochs, H. Dieter, Aug: 63
Offenhauser engine, May: 57-60
Oil leaks, Jan: 62-63; Sep: 92
Oil pumps, Mar: 47-49; Oct: 57
Oldsmobile, Jul: 38
cam/fuel pump imcompatibility in '76-77s, Dec: 48
challenge to Ford's position, Nov: 37
Cutlass ('81), May: 10, 75
Cutlass Ciera tune up specs, Jan: 74
Delta 88, Jul: 38
diesel ('81), whistling noises, Oct: 61
Misar, ignition timing, Mar: 37
Multi-Function tone generator failure in '78s, Apr: 10-11
sales strategy, Mar: 65
Omni (Dodge)
carburetor mounting, Feb: 9
disc brake piston, Sep: 88
disc brake service, Dec: 49
distributor pickup, Feb: 62
front suspension noise, Jun: 35
isolator plates, Jul: 10-11
mileage problems, Mar: 12, 56
rear brake noise, Jun: 66-67
throttle shaft wear, Oct: 12
transaxle problems, Oct: 60
vacuum leak, Jul: 10-11

wheel bearing failure, Jan: 61
Opel, transmission fluid for, Sep: 32
Original equipment(OE) suppliers, Oct: 42
Oscilloscope tests, May: 78

P

Paint, Body & Equipment Association, The, Mar: 59
Paint protectors, Jan: 64
Partially Stabilized Zirconia(PSZ), Dec: 44
Parts (general information)
aftermarket, ID marking, Mar: 64
for early Porsches, Dec: 64
generic names for, Mar: 64
gypsy, Mar: 66
higher-priced, May: 84
interchangeable, Apr: 38
original equipment, Dec: 34
overseas sources, Nov: 35
recycled, Mar: 82; Jun: 51
replacement, Mar: 68, Jun: 52; Oct: 41; Dec: 34
used, dwindling supplies, Feb: 54
Parts (specific), supplies, accessories
AC condensers, Dec: 64
anti-theft device, Nov: 61
automatic transmission fluid conditioner, Dec: 61
bearings, Nov: 69
brake lathe parts, Dec: 69
clips and fasteners, Dec: 58
cooler, Sep: 95-96
"courtesy check" tags, Nov: 66
distributor caps, Nov: 59
electrical accessories, Sep: 94
exhaust line, import, Nov: 65
fuse holder, Dec: 66
glow plugs, Dec: 62
oil coolers, Sep: 98-99
rack and pinion units, remanufactured, Aug: 72
radiators, Dec: 60
replacement gas-charged lift supports, Dec: 60
re-ring kits, Feb: 48
seal interchange guides, Jun: 69
seals, Nov: 69
shock absorbers, Oct: 75-76; Nov: 60; Dec: 58
spark plugs, Nov: 64-65
spark plug wires, Oct: 72
strut cartridges, Nov: 64
thermostat, replacement, Dec: 63
transmission sleeves, Oct: 71-72
V-belts, Aug: 71; Dec: 62
warning systems, Oct: 68-69
Water Watcher and Remote Discharge Valve, Nov: 61-64
Parts industry
counterfeiters and, May: 85
GM/Toyota venture and, Apr: 35
Japanese, Dec: 35
private branding, May: 84
use of robots by, Jul: 52
Pascal's Law, Dec: 27
Perry, Harold A., Jul: 55
Petty, Richard, Jun: 76
Peugeot, Mar: 88, Sep: 32
Phone support, Dec: 36
Pistons
damage from detonation, Mar: 70, 73
markings in Escort/Lynx, Oct: 61
Pit crew competition, Aug: 47
Plymouth
ignition problems, Jan: 10, 15
Miser ('82-'83). *See* **Miser (Plymouth)**
pistons, pins, rings, crankshaft, and bearing specs, Nov: 70
Reliant. *See* **Reliant (Plymouth)**
vans ('79-'82), starter relay, Jun: 67
Voyager, front/rear a/c, Jun: 19
Plymouth-AAA Trouble Shooting Contest, Oct: 64
Pocock, Gordon, Aug: 64
Polimotor Research, Nov: 8-9
Polishing, Mar: 55
Pontiac
oil filter bypass valve ('77-'83s), Jun: 67
radial tire replace, Mar: 90
Pontiac Fiero, Feb: 47; Sept: 16, 20-21, 75, 78; Oct: 49
Pontiac Firebird ('82-'83), radio replace, Mar: 90
Pontiac 1000, starting motor, tune up, and wheel alignment specs, May: 106
Pontiac 2000, 50 mpg EPA rating, Jan: 51
Pontiac 6000, knocking noise, Dec: 49
('82-'83), tune-up specs, Jan: 74
Pontiac Phoenix ('83), thermostat housing sealant, Sep: 88, 90
Pontiac THM 700-R4, TCC solenoid wire, Aug: 75
Pontiac T1000 ('81), burned valves in, Jun: 55
Porsche
cooling system and capacity data, Feb: 80
1983 models, Jan: 27-28
parts for early, Dec: 64
transmission fluid for, Sep: 32
tune up specs, Feb: 80
Ported vacuum advance, Oct: 38
Positive Crankcase Ventilation (PCV) system, Jan: 41-44
Posters, pin-up, Dec: 36
Potholes, Jan: 52
Precision Universal Joint Corporation, Jul: 53
Preheated intake air system, Jan: 46-49
Prelude ('80), shifting, Dec: 54
Pressure plate inspection, Sep: 49-50
Pressure washer, Mar: 83; Jul: 67
Prices, dealer and, Jul: 35
Private branding, May: 84
Probe IV (Ford), Feb: 47
Project START(Service Technician Advancement Recruitment & Training), mechanics' self-image and, Feb: 55
Pro Trac Tire, Jul: 55
Pulse Air Injection(PAIR) system, Jun: 30, 59-61
Pumps
auxiliary, in Toyotas, Mar: 49
in-tank, Jul: 32
oil, in Hondas, Oct: 57

Q

Quadrajet M4M series adjustment specs, Sep: 102
Quota imports, Oct: 43

R

Racing, Feb: 47; Dec: 41-43
Rack and pinion steering, sluggish, Sep: 10
Radar reading, Jul: 54
Radiators
of Escort/Lynx/LN7, May: 41-42
knock, in Volvo 240 and 260, Jul: 59
rebuilding, May: 41-46, 92
cleaning core, May: 46
core repair, May: 46
tank removal and replacement, May: 42-46
testing procedure, May: 46, 92
Ram 50, upper control arm replacement, Feb: 80
Ranking, car company, Nov: 36
Raybestos, Aug: 56
Raymark Corp., Mar: 59
Rear-wheel vs. front-wheel drive, Jul: 37
Recalls
carmakers' against, Aug: 52; Dec: 35
of GM pickups and 4 X 4's, Feb: 64
of X-cars, Sep: 6, 63
Reliant (Plymouth)
chuckling noise, Sep: 88
front suspension noise, Jun: 35
rear brake noise, Jun: 66-67
transaxle problems, Oct: 60
Renault
transmission fluid for, Sep: 32
VESTA research vehicle, Feb: 47
wiring abrasion, Dec: 54
Repairs, cost of, Aug: 61
Republic Parts, Apr: 37
Resonators, Oct: 48
Respirator systems, Apr: 65
Rest pressure test, Jul: 30

Restraints, passive, Oct: 10, 50-51
Rexnord, Inc., Dec: 47
Robert Bosch GmbH, Jun: 41
Robertson, A. Barclay, Aug: 63
Robot(s), May: 86; Jul: 17-20, 52
Robot Institute of America(RIA), Jul: 19
Rochester 2SE and E2S3 adjustment specs, Apr: 70
Rolls-Royce, Jun: 54
Rota, Ray E., Aug: 63
Rothsmans-Porsche 956, Jun: 41
RTV silicone sealers, Dec: 23-25
Run-on, Jul: 21
Russell, Thomas F., Mar: 42
Rustproofing, caution in, Dec: 49

S

Saab
99 ('72), frozen cylinder head, Aug: 11
sales, May: 67; Aug: 62
service bulletin no. 04/83-624, Sep: 10
starting problems, Dec: 54
transmission fluid for, Sep: 32
Turbo Cabriolet, Dec: 44
Turbo special edition, Mar: 57
valve clearance check, Jul: 59
warranty, Jul: 53
S-A Design Publications, Jun: 76
Sanding, Mar: 54; Apr: 65
Sales, Jan: 18; May: 67; Jul: 38; Aug: 61, 62; Dec: 18, 45
Sattler, Raymond, Jul: 49-51
Saturn, Dec: 33, 34
Schwoebel, James D., Aug: 63
Sealants, May: 39; Jun: 69; Dec: 23-25
Seat belts, Jul: 59; Oct: 10, 50-51
Sebok, Paul, Aug: 64
"Service Slants"
Alliance
shift rod adjust in '83s, May: 90
transaxle problems in '83-'84s, Nov: 56
Aries/Reliant
chuckling noise in '81-'82s, Sep: 88
rear brake noise in '81s, Jun: 66-67
transaxle problems in '81s, Oct: 60
Buick ('80-'81) light throttle detonation, Jul: 57
Cadillac ('81)
cold engine noise, Jun: 66
MAP sensor line icing, Jan: 61
Chevrolet
dwell reading in '81s, Oct: 61
EGR valves in '83s, Sep: 88
Chryslers
accelerator pump adjust, May: 91
differential fill plug in FWD automatic transmission, Aug: 75
hesitation or sag in trucks, Dec: 49
ignition components, digital circuit, Apr: 62
manual transaxle in '83s, Feb: 64
power steering shudder in FWDs, Jul: 57
2.2 liter oversize camshaft markings, Oct: 61
valve spring change in '81-'83s, Aug: 75
Corvette ('65-'79) disc brake service, Oct: 61
diesel fuel, contaminated, Dec: 48
Dodge vans ('79-'82), inoperative starter relay, Jun: 67
Escort/Lynx
brake booster replace, Jul: 57
piston markings in '81-'83s, Oct: 61
power lack in '82s, Sep: 88
steering wheel return in '81-'83s, Jul: 57
EXP/LN7 brake booster replace, Jul: 57
Fairmont/Zephyr
brake caliper changes in '79s, Jun: 66
stalling while parking in '81s, Dec: 48
Ford
a/c spring lock couplngs in '81-'83s, May: 90
detonation problems in '80s, Sep: 90
FM radio interference in '77-'81s, Oct: 61
460 cid engines main bearing knock in '75-'77, Aug: 75
full-lock turn stalling in '78-'81s, Sep: 90-91
power rack and pinion replacement parts in '79s, Mar: 68
strut diagnosis, Jan: 61
3.8 liter engine spark plug change, Feb: 62
GM
diesel fuel filter test, Sep: 91
diesel injection pump fuel shutoff solenoid, Dec: 49
distribution service for HEI ignition equipped, May: 91
ECM malfunction in '82-'83 diesels, Sep: 91
restricted exhaust in '82-'83s, Dec: 48
THM 200-4R buzzing, Dec: 49
THM 700-R4 gear failure in '82-'83s, Oct: 61
2.5 liter gear noise, Nov: 56
wheel failure in pickups and 4 X 4s ('82), Feb: 64
Granada/Cougar ('81)
rear shock clunking noise, Dec: 49
stalling while parking, Dec: 48
HEI ignition mounting screws, Jul: 57
hot restart problems in diesels, Feb: 62-64
hydraulic lifters, noisy, Feb: 62
Impala/Caprice ('81 diesels) diode service, Dec: 49
Jeep ('81) water pump and fan assembly, Mar: 68, 72
LeBaron/400 chuckling noise, Sep: 88
LeSabre/Electra ('80) blower motor problems, Dec: 49
Lincoln/Mercury
power rack and pinion replacement parts, Mar: 68
full-lock turn stall, Sep: 90-91
strut diagnosis, Jan: 61
Miser ('82-'83) spark knock, Mar: 68
Mustang/Capri
brake caliper changes in '79s, Jun: 66
fluid check, Nov: 56
stalling while parking, Dec: 48
Oldsmobile
cam/fuel pump incompatibility in '76-'77s, Dec: 48
diesel ('81) whistling noise, Oct: 61
Omni/Horizon
disc brake piston in 83's, Sep: 88
distributor pickup, in '78-'79s, Feb: 62
front disc brake service for '78-'83s, Dec: 49
rear brake noise in '81s, Jun: 66-67
transaxle problems in '81s, Oct: 60
wheel bearing failure in '78-'80s, Jan: 61
Phoenix ('83) thermostat housing sealant, Sep: 88, 90
Plymouth vans ('79-'82) inoperative starter relay, Jun: 67
Pontiac
oil filter bypass valve in '77-'83s, Jun: 67
6000 ('83) knocking noise, Dec: 49
THM 700-R4, TCC solenoid wire, Aug: 75
rustproofing, caution in, Dec: 49
Skylark ('82) insufficient a/c, Apr: 62
Tempo/Topaz ('84) oil spill-over, Oct: 61
THM 200-4R transmission noise, Apr: 62
valve guide and stem wear, Oct: 60
welding, galvanized and Zincrometal, Jan: 61
Service Station Dealers of America, Inc., Mar: 59
760 GLE ('83), Jan: 27
Shelby-Chrysler Performance Center, Jun: 76
Shell Oil Co., gas sales policy, Jan: 51
Shock absorbers, Dec: 49
Showich, Nicholas A., Aug: 63
Siekierda, John T., Jul: 55
Sierra, Jul: 36
Silencer bands, Jun: 68
SKF Industries, Inc., Oct: 44; Dec: 47
Skylark (Buick)
insufficient a/c, Apr: 62

rear suspension squeaking, Jun: 36
Small Business Motor Fuel Marketer Preservation Act, Jun: 41
Smart, Robert A., Jr., Aug: 63
Smith, Glenn, Aug: 64
Smoot-Hawley tariff, Mar: 8
Smyrna plant, Dec: 33
Society of Automotive Engineers, Feb: 56; Aug: 14-18
Solenoid, a/c, Jul: 21
Somerset, Jul: 37
Spark advance vacuum modulator (SAVM), Oct: 38-39
Spark knock, Mar: 68, 70, 73, 81-82; Sep: 64
Spark plugs, Feb: 62; Mar: 73
Specialization, Apr: 44; Sep: 61
Speed limit, Dec: 35
Sperlich, Harold K., Sep: 26
Sports car, children's, Jul: 66
Sportsman, front/rear a/c, Jun: 19
St. Regis ('79), torque converter clutch slippage, Feb: 10-11
Starlet ('81-'83), self adjusting clutch, Dec: 53
Steele, H. William, Jul: 55
Steering
column, Toyota, Mar: 49-50
power, in Chrysler FWD, Jul: 57
rack and pinion, Sep: 10
"Steering and Suspension Update," Jun: 35-37
Stempel, Robert C., Sep: 21
Stu Evans Lincoln-Mercury Southgate, Inc., Oct: 22
Styling, Jan: 52
Subaru
BRAT, Sep: 75
FWD, Sep: 62
GL Brat ('83), May: 69
transmission fluid for, Sep: 32
Sun Electric, Jan: 55
Suspension systems. *See also* MacPherson struts
air, for Mark, Apr: 45
electronic, Dec: 45
front end noise in Omni/Horizon, Jun: 35
in Skylark, Jun: 36
Suzuki, hatchback, Nov: 53

T

Tax(es), Jun: 54; Nov: 37
"Tax Tips"
business mileage, Jul: 68-69
education expenses, Feb: 74-77
equipment
loss coverage, Feb: 73-74
used, Sep: 83, 87
fraud, Dec: 56-57
home-office deductions, May: 102-103
insurance, business interruption, Nov: 57-58
investment tax credit, Sep: 83, 87
T-cars, Feb: 55
Team service, Oct: 21-23, 54
Temperature control, electronic, Nov: 42-44
Tempo (Ford), Apr: 26-31, 59
chassis, Apr: 59
diesels, Jul: 38; Sep: 39
drive train, Apr: 28-31, 59
introduction, Jul: 54
marketing of, Apr: 31
oil spill-over, Oct: 61
1.6 liter engine option, Jan: 58
performance engines for, Sep: 62
support, Nov: 53
towing, May: 83
Temporary crisis theory, Jan: 6
Tercel (Toyota)
self adjusting clutch, Dec: 53
wagon ('83), Jan: 20
Throttle body fuel injection(TBI), Mar: 33; Sep: 26
Thrust bearing, Jul: 12-13; Oct: 57
Thunderbird (Ford)
fluid check, Nov: 56
hot starting problems, Nov: 10
thrust bearing wear, Jul: 12-13
Turbo Coupe ('83), Apr: 31, 59-60
Tie-rod testing, Mar: 12
Timing, May: 20, 78; Oct: 37-38. *See also* Ignition systems, timing procedures
Tires
bead sealers, May: 98
P8 (Pirelli), Jan: 52; Mar: 58
radial, Mar: 57, 90; Jun: 37
Tool makers, Detroit and, Jan: 55
Tool(s), repair kits, equipment
abrasive rolls, Apr: 65
air tank kits, Jul: 66
analyzers
starting and charging system, Aug: 67
engine, Oct: 43
assembly tools, Sep: 95
battery cable repair kits, Dec: 68-69
battery chargers, May: 98
bits, May: 98; Jun: 23
body repair tools, Jan: 68
brake, rear, adjuster repair kits, Aug: 67
brake bleeders, Mar: 75; Jun: 69; Dec: 28
brake caliper rubber seal spreader, May: 77
cabinets, Feb: 47; Dec: 63
camber correction tool, Mar: 75
carburetor floats, Dec: 68
charging stations, Jun: 68
cleaners, Dec: 66
brake, Feb: 68
degreaser and engine, Dec: 60
electrostatic precipitator air, Nov: 69
hand, Jan: 72
liquid tar and bug remover, Dec: 59
solvent, Oct: 73
cleaning tanks, Aug: 69-71
collision repair system, Dec: 61-62
compressor
air, Mar: 82-83
methane, Feb: 58-59
cooling system flusher, Oct: 77
crankshaft stroke gauge, Oct: 74
creepers, Mar: 84; Jul: 67
crimping tool, Nov: 59-60
cut-off, air-operated, Apr: 64
cutting tools, Sep: 10
drills
angle, Jun: 22
bits, May: 98; Jun: 23
cordless, Mar: 75
dynamometer, liquid nitrogen-cooled, Dec: 44
expanders, piston ring, Jun: 72
flashlights, Vari-Beam, Jun: 23
fusepuller, Jun: 22
gasket material, Nov: 65
grease, high temperature, Dec: 67
hammers, dead blow, Jun: 22
hitch receivers, Oct: 72
hoists, chain, Jun: 72
hole saw kits, Jun: 68
hose reels, Aug: 72
hydraulic puller, Sep: 97
impact tools, Oct: 77
injector tool kit, Nov: 60
inspection lights, Nov: 67-69
jacks, hands, Oct: 69-70
lamp kits, Jul: 66
lathes, brake
centering cone, Sep: 97
combination, Jan: 68
disc, Nov: 61
molding guide, Jun: 23
muffler stand, Oct: 76
nut starter, Jun: 22
piston-engine borescope kit, Oct: 76-77
primers, aerosol, May: 98
puller set, Oct: 71
pump transfer, Nov: 66-67
radial compressor conversion kits, Sep: 96
reverse clutch housing remover, Mar: 77
sander grinder, Sep: 99
Sav-A-Thread, Jun: 22
screwdrivers, May: 99; Jul: 65; Dec: 64
separator, fuel/water, Dec: 67-68
solvent wipes, Jan: 64
spray booths, Jan: 64; Dec: 66
stand and crane, Sep: 96-97
surface lift, Oct: 74
tachometers, Oct: 70-71
tapes
attachment, Oct: 69
self-adhering safety, Dec: 69
TBI(throttle body fuel injector) repair kit, Dec: 66

telephones
coin-operated, Dec: 66-67
cordless, Dec: 59
temperature probes, Aug: 68
testers
C-3, Apr: 22-25, 52-57; Dec: 63-64
Chrysler electronic engine control system (Part #C4805), Nov: 26
Custom III Cruise Control System, Dec: 60
cylinder leakage, Dec: 69
dye-penetrant, kit, Oct; 75
ignition module/voltage, computerized, Dec: 61
module, Oct: 68
timing kits, Dec: 64
tire repair kits, May: 99
torsion spring twister, Jun: 23
transmission tools, Aug: 67
tubing kit, Jul: 66
vacutector, Aug: 71-72
vacuum
asbestos, Feb: 68; Dec: 69
pumps, Jun: 22
vehicle detector, Dec: 58
volt/amp meter, Sep: 94
welders, Aug: 68-69
MIG, portable, Dec: 69
push-pull gun, Dec: 62
spot/pulse, Jul: 67
wheel aligners, Jan: 69; Jun: 69; Sep: 94; Oct: 69
wheel balancers, Mar: 85; Jul: 67; Sep: 95
windshield repair kits, Jan: 73
wreckers, May: 99
wrenches
air control valve, Dec: 66
strut, Sep: 99-100
Topaz (Mercury), Apr: 26-31, 59
chassis, Apr: 59
diesels, Jul: 38; Sep: 29
drive train, Apr: 28-31, 59
introduction, Jul: 54
marketing of, Apr: 31
oil spill-over, Oct: 61
1.6 liter engine option of, Jan: 58
performance engines for, Sep: 62
support, Nov: 53
towing, May: 83
Torx keys, Jul: 66
Toyo Kogyo, Apr: 45
Toyota
automatic transmission, May: 94-96; Jun: 63-65
auxiliary pumps, Mar: 49
Camry ('83), Mar: 57
distributor rotors, Sep: 82
electronic ignition system points, Mar: 46
Celica, Jan: 20
Cressida, Jan: 20; Mar: 46
1983 imported cars, Jan: 20
oil filter repair, Mar: 50
seat belt relay in '74s, Jul: 59
service problems, Mar: 45-50
starter replace, Nov: 70
steering column, Mar: 49-50
throttle cable adjust, May: 94
Supra ('81-'82), Jan: 20; Mar: 46
Tercel. *See* **Tercel (Toyota)**
transmission fluid for, Sep: 32
Toyota-GM partnership
Chrysler and, May: 83
"foreign imports" and, Apr: 38
in-house reactions, Sep: 60
Japanese production secrets and, Apr: 36
negotiations, Jan: 57
parts business and, Apr: 35
possible consequences of, Dec: 34-35
Trade, international, loca content legislation vs., Mar: 8
"Trade Secrets"
Cadillac ('81) power steering/power brake problems, Mar: 16, 67
check guarantee service, Mar: 67
Chrysler ('79) aspirator valve failure, Nov: 18-19
Colt ('80) catalytic converter, Dec: 14
customers, flexibility with, Jun: 12
Cutlass ('81) C-3 engine control system, May: 10, 75
driver characteristics and warranties, Sep: 12, 67
Oldmobile ('78) Multi-Function tone generator failure, Apr: 10-11
Plymouth ('75) ignition problems, Jan: 10, 15
St. Regis ('79) torque converter clutch slippage, Feb: 10-11
thrust bearing wear, Jul: 12-13
Torque Flite transmission problems, Aug: 12-13
Vega ('77) overheating, Oct: 16, 53
Transaxles
A-460, Oct: 60
in Alliance ('83-'84), Nov: 56
in Aries/Reliant ('81), Oct: 60
manual, in Chrysler ('83), Feb: 64
oil change recommendations for '83 Chryslers, Feb: 64
in Omni/Horizon, Oct: 60
Transmissions
automatic, Toyota, May: 94-96; Jun: 63-65
auxiliary, Jul: 65
bearings, noise test for, Sep: 48-49
filters, Sep: 31-41
fluid, Sep: 32, 41-42
gear rollover test, Sep: 48-49
T-5, Nov: 56
THM
leak diagnosis, Dec: 55
200-4R noise, Apr: 62
700-R4, TCC solenoid wire, Aug: 75; Oct: 61
Torque Flite, Jan: 8; Aug: 12-13
Toyota 5-speed, Mar: 49
tuneups, Sep; 31-44
filters and, Sep: 31-41
intervals, Sep: 41-42
Triple A, Oct: 44
Triumph, transmission fluid for, Sep: 32
"Troubleshooter"
Aspen ('77)
brake bind, May: 8
cold running, May: 8
front wheel lock up, Feb: 8
Cadillac Sedan DeVille alignment problem, Jan: 8-9
Chevette
fuel system, in '79s, Aug: 10-11; Nov: 10
Hatckback ('80) steering wheel shakiness, Feb: 8
Chevy 3.8 liter cold driveability problems, Dec: 12-13
Chryslers, cold driveability problems, Aug: 10
CIS hot start problems, Oct: 12, 52
EEC IV computer-equipped Fords, timing adjusts, Jun: 10
Econoline ('61) van generator light problems, Jun: 55
Fairmont ('79) driveability and stumble problem, Apr: 8; Jul: 10
float bowl fuel loss, Jul: 10
Ford F350 ('79) fuel vaporization problems, Nov: 10-15
Ford van ('78) fuel vaporization problems, Nov: 10-15
head gasket retorquing, Oct: 52
LUV ('74) pickup linkage, Jan: 9
Malibu
mixture problems, Sep: 64
pinging, Jun: 10, 55
Monaco ('77) handling problems, Feb: 8-9
Nova ('68) oil dilution problem, Apr: 8-9
Omni/Horizon
carburetor mounting, Feb: 9
isolator plates, Jul: 10-11
mileage problems, Mar: 12, 56
throttle shaft wear, Oct: 12
vacuum leak, Jul: 10-11
Pontiac T1000 ('81), burned valves, Jun: 55
rack and pinion steering, sluggish, Sep: 10
Saab 99 ('72) frozen cylinder head, Aug: 11
spark knock, Sep: 64
Thunderbird ('68) hot starting problems, Nov: 10
tie-rod testing, Mar: 12
Torqueflite transmission trouble, '79 Plymouth, Jan: 8
Trucks
sales, Dec: 45
turbocharged diesel, Apr: 14-18, 46-50
Truth in Lending Act, Apr: 6
Tuneup(s), May: 15-21, 78-79
average cost of, Apr: 38

cold start comebacks, May: 20
diagnostic routine, May: 15-20
power balance, May: 78-79
scope reading, May: 78
spark timing tips, May: 20, 78
Tune-up Manufacturers Institute (TMI), Sep: 78
TVR Tasmin, Jun: 46
Type F transmission fluid, Sep: 32

U

Ultra, Aug: 61
Unemployment figures manipulation, Oct: 43
Unit body cars, metal repair problems, Mar: 65
United Parts Division of Echlin, Inc., Mar: 57
Used equipment, Sep: 83, 87

V

Vacuum breaks, Jul: 23-24, 28-29
Vacuum spark control devices, Oct: 37-39
Valve(s)
auxiliary, in Hondas, Oct: 32, 56
burned, in T1000, Jun: 55
deceleration, Jul: 21-24
distributor vacuum delay(DVDV), Oct: 39
EGR, Feb: 19-20, 21; May: 20
thermal vacuum(TVV), Jan: 20
vacuum reducer(VRV), Oct: 38
Valve guide and stem wear, Oct: 60
Vanagon (Volkswagen) water-cooled engine, Jul: 63-64
Van Wagon, Nov: 50
Vapors, gasoline, danger of, Oct: 63
Vehicle Multiple Listing Network (VMLN), Jul: 53
Vehicle theft, Feb: 54
Volkswagen
ignition timing procedures, Mar: 41
Jetta, Jan: 27
1983 models, Jan: 26-27
retail leasing by, Jul: 53
3508 mpg car, Jan: 51
transmission fluid for, Sep: 32
Volkswagen-Chrysler deal collapse, Oct: 42
VW Quantrum ('83), Jan: 27
VW Rabbit
Diesel ('83), Jan: 27
80 mpg, Jan: 12
front end clunking noise, Dec: 53
GTI ('83), Jan: 24, 26-27
VW Vanagon, water cooled engine, Jul: 63-64
Volvo, Jan: 27; Mar: 58
clutch repair in '79s, Sep: 50
140, sump removal, Sep: 82
transmission fluid for, Sep: 32
240 and 260, radiator knock, Jul: 59

W

Wagner, Mar: 58; Aug: 56; Dec: 45-46
Walker Manufacturing Company, Mar: 59; Jun: 43
Warehouse distributors, discounts offered by, Apr: 36
Warranties, driver characteristics and, Sep: 12, 67
Wastegates, turbocharger, checking, Sep: 53-56
Weed Currie, Oct: 54
Welding
clamping vs., in exhaust systems, Oct: 48
contact lens use and, Jun: 52; Jul: 37
of galvanized or Zincrometal panels, Jan: 61
Westfield Sports Cars, Jul: 53
Weston, Richard, Aug: 63
Whitehead, Lewis E., Jr., Oct: 23
Windows, power, May: 98
Windshield wipers, neglect of, Jan: 51
Winnebago Industries, Jun: 43
Wolter, James G., Jul: 55
Working conditions, mechanics', Feb: 6-7
Worth Manufacturing, Nov: 53

X

X-cars (GM), Apr: 35, 37
clutch repair tips, Sep: 45-48
brake problem in, Aug: 6-7
recall, Sep: 6, 63

Z

Zephyr (Mercury)
brake caliper changes, Jun: 66
stalling while parking, Dec: 48
Ziebart, Aug: 54